



## AN/TPQ-36(V)8 Firefinder Radar Repairer Training

### Scope

- Blended instructor-led and self-paced intermediate courseware
- 159 hours of level II and III interactive multimedia instruction
- Over 40 self-paced interactive fault isolation practical exercises

### Highlights

- Technology infusion improved 94M maintenance training effectiveness
- Supported replacement of inefficient hardware trainers
- Delivered capability to reduce course length by at least 20%



ISO 9001:2008 CERTIFIED



11315 Corporate Blvd., Suite 100, Orlando FL 32817 • 407-207-3550 • corsairengineering.com